

LT Propeller

**HARTZELL**

# PROPELLER LOGBOOK

PROPELLER MODEL HC-E3YR-2ATF

PROPELLER S/N DJ-10668A

LEFT  
PROP

2

START

2/08

END 11/10

LOGBOOK # \_\_\_\_\_

N109B 4H Prop

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

## PROPELLER MAINTENANCE RECORD

Position \_\_\_\_\_

Propeller Model HC-~~E3~~VR-2ATF

Propeller S/N DJ-10668A

Blade Design FC8468-6R

Blade S/N's

No. 1 K 12272

No. 2 K 12273

No. 3 K 12275

No. 4 \_\_\_\_\_

No. 5 \_\_\_\_\_

No. 6 \_\_\_\_\_

Spinner Assembly Part No. \_\_\_\_\_

## PITCH RANGE

High/Feather \_\_\_\_\_

Start Lock \_\_\_\_\_

Low \_\_\_\_\_

Reverse \_\_\_\_\_

Aircraft Manufacturer \_\_\_\_\_

Aircraft Model \_\_\_\_\_

S/N \_\_\_\_\_

Registration \_\_\_\_\_



Propeller		A/C	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
TSN	TSO	Hrs	
<p>September 11, 2013</p> <p>FLUSH HARTZELL PROPELLER (DWG# HC-E3YR-2ATF) (SERIAL#D)10668A) I/A/W: HARTZELL MANUAL 117-D Mechanic making installation must comply with FAR 43.9. Repair Station DM2R773K certifies this propeller is airworthy wjth respect to the work performed. SIGNED: <u>Kenneth Kohn</u> San Antonio Propeller Service, Inc.</p>			<p>W/O 17210</p>

1-27-15 Gemini Aviation LLC dba DUGOSH  
N10QB 1875 Airport Loop, # 105  
Hobbs: 2754.7 Kerrville, Texas 78028  
Left Propeller 830.315.2222

I certify that have inspected this propeller IAW an Annual/100 hour inspection,  
and it was found to be airworthy and is returned to service.

Robert Fenner AP 378806656-1A

Robert Fenner

				Hobbs	
3-9-17	4046.4	1297.5	2936.5		<p>C/W ANNUAL INSPECTION OF Propeller per Piper S. + M. Manual for  PA-31-325. Propeller Found to be in airworthy conditions for  return to service. All A.D.'s checked thru 2017-05.  <u>David Behnam AIP 2804926 I&amp;A</u></p>

# SAN ANTONIO PROPELLER SERVICE, INC. SERVICEABLE PARTS TAG

Work Order 17210

Customer Order No. \_\_\_\_\_

Customer's Name Kerrville Aviation

Part Name Propeller Part Mfg. Hartzell

Part No. HC-E3YR-2ATF Serial No. DT1066BA

Remarks Flush Only I/A I/W Hartzell Manual  
117-D

pertaining to Airworthiness Directives,  
II, Major or Minor Repair, and Inspections.

ac'd. N/A Reworked By: N/A  
is Checked By: N/A Alodined By: N/A NDI By: N/A  
Base N/A Low N/A High N/A Painted By: N/A  
Discrepancy Report Sign-off Document Rev. N/A  
Mech/Initials \_\_\_\_\_

## MAINTENANCE RELEASE

This stamped paper is an official document and shall be kept with  
the AIRCRAFT'S OFFICIAL HISTORICAL RECORDS. Work  
completed under the above listed work order number is on file  
this agency. The above component was repaired and/or  
replaced in accordance with the current FEDERAL AVIATION  
REGULATION, ground functionally tested and approved for return  
service subject to Flight Operational Test. The mechanic making  
installation must C/W FAR 43.9

Signed Kenneth [Signature]  
Date Sept 11, 2013  
San Antonio Propeller Service, Inc.  
234 W. Turbo, San Antonio, Texas 78216  
FAA Approved Repair Station No. DM2R773K

Ret'n. N/A Installed By: N/A

1-27-15 Gemini Aviation LLC dba DUGOSH  
N10QB 1875 Airport Loop, # 105  
Hobbs: 2754.7 Kerrville, Texas 78028  
Left Propeller 830:315.2222

I certify that have inspected this propeller IAW an Annual/100 hour inspection,  
and it was found to be airworthy and is returned to service.

Robert Fenner AP 378806656-1A [Signature]

Hobbs

3-9-17 4046.4 1297.5 2936.5 C/W ANNUAL INSPECTION OF Propeller per Piper S. & M. Manual for  
PA-31-325. Propeller found to be in airworthy condition for  
return to service. All A.D.'s checked thru 2017-05.

David Behnam AIP 2804926 I/A



