

AIRCRAFT LOG

NC N776GA

DESCRIPTION

AIRCRAFT MFG. Gulfstream American MOD. GA-7 SER. NO. GA7-0065
 AIRCRAFT COLOR _____ SPAN _____ LENGTH _____ DATE MFG. 1978
 ENGINE MFG. Sydney 4H MOD. 0-320-DID SER. NO. L-7824-39A
 ENGINE MFG. Sydney RIH MOD. 0-320-DID SER. NO. L-8338-39A
 PROP. MFG. Hartzell HUB MOD. HC-F24K-21F SER. NO. QFE-173
 BLADE 4H D-98140 SER. NO. D98185 SER. NO. D98158 SER. NO. D89309
 SEAT CAP. _____ EMPTY WT. _____ GROSS WT. 3800 BAG. WT. _____
 FUEL CAP. _____ LEFT TANK _____ RIGHT TANK _____ TOTAL USABLE _____ OIL CAP. _____ GALLONS _____

GRUMMAN AMERICAN AVIATION
 CORPORATION

revised items, a

0120

NC

[illegible]

though reported, do not



ARTEX AIRCRAFT SUPPLIES, INC.
14405 Kell Rd. NE Aurora, OR 97002
(503) 678-7929 800-547-8901

LOG BOOK ENTRY
E.L.T. BATTERY
REPLACEMENT DATE

Nov. 2008

Begin
10/20/95

Gulfstream American

Gulfstream American Corporation
P.O. Box 2206 Savannah, Georgia 31402

601-956-2483

N776GA

AIRCRAFT LOG

Technical data.

NSN: 0052-00-012-9005

ENG. SER.

DATE 19__ TAC
TIM

Date 11-11-02 N 776GA TACH _____ HOBBS 0202.4

Replaced all brakes and shoe retaining pins, sealed R+L wheel cylinders. Replaced L elevator tip, cleaned + packed wheel bearings. Retract performed. Serviced hyd. unit + batteries. Checked all controls. Replaced ELT battery. Replaced all inspection covers after inspection.

ELT Replace date Nov. 2004 Annual

This aircraft has been inspected in accordance with Appendix D of FAR part 43 and Cumma inspection guide and was considered to be in an airworthy condition at this time.

Buddy's Aircraft Service, Inc.

7504 Old Canton Road

Madison, MS 39110

601-856-5020 phone

601-856-7671 Fax

M. H. Bowering

AP 1707558 I A

M.H. Bowering

FORWARD
TOP OF NEXT

AND
NO.

AND
NO.

DATE
19

Date 12-1-03 N 776GA TACH HOBBS 0263.2
Replaced nose wheel tire; tube. 15x600x6 Mich.
Aviator. 15x600 tube. Replaced air: vacuum
filters. Installed new seals in right main gear.
Serviced battery: hyd. system.

This aircraft has been inspected in accordance with Annual inspection as outlined in
Appendix D of FAR part 43 and human inspection guide and was considered to be in an
airworthy condition at this time.

Buddy's Aircraft Service, Inc.
7504 Old Canton Road
Madison, MS 39110

601-856-5020 phone
601-856-7671 Fax

M. H. Bowering
AP 1707558 FA

M. H. Bowering

IONS
FACILITY

NSN: 0052-00-012-9005

ENG. SER.

DATE

19__.

Date 1-14-05 N 776GA TACH

HOBBS 0327.7

RE AND
ATE NO.

DATE
19__

Replaced vacuum filter. Changed battery.
Replaced rod end bearings on gear doors.
Overhauled Shimmy dampers. Replaced ELT Batt.
p.n. 00-10-009. Packed wheel bearings. Performed
retract. Juled gear, checked all controls.
Replaced aircraft battery p.n. G 25 D 5 n.
G02183492. Serviced with Acid

ELT Batt. expires Feb. 07.

This aircraft has been inspected in accordance with ~~Summary~~ *Final* inspection as outlined in Appendix D of FAR part 43 and was considered to be in an air-worthy condition at this time.

Buddy's Aircraft Service, Inc.
7504 Old Canton Road
Madison, MS 39110

601-856-5020 phone
601-856-7671 Fax

FORWA
TOP OF

M. H. Bowering
AP 1707558 IA

M.H. Bow

DATE 19__	TACH. TIME	THIS FLIGHT	TOTAL TIME	REMARKS	NC SIGNATURE AND CERTIFICATE NO.
10-7-05		HOBBS:	368.8	Removed auto-pilot elevator trim servo, sent to AutoPilot Central Inc. w.o # SH05-10792 dated 9/28/05. Reinstalled as per GA-7 Maint. Manual. M.H. Bow AIP 1707558	
FORWARD TOTALS TO TOP OF NEXT LEFT PAGE					

FORWARD TOTALS TO
TOP OF NEXT LEFT PAGE

[illegible]

FORWARD TOTALS
TOP OF NEXT LEFT

