


RT



PROPELLER SERVICE, INC.

A -PS4R451M

**rlington - Alamance Regional Airport
rlington, NC 27215**

**Propeller Logbook
(336) 227-1467
1-800-334-6437**

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
31 July 08		Overhauled propeller m/n HC-F2YL-2	
		S/N FF77 C/W SB 226 R1, 136 I, 118 F, 8 L	
		61-61 R1, 154, 177, 223, 228, 217, 229, 282	
		SI 152 A, AD 107-13-28 greased, painted	
		and balanced by JH & JH Propeller	
		Service Enclosure WO # 169150	
		H & H PROPELLER SERVICE, INC.	Prothman Jao Corp
		3439 SOUTH AVIATION DRIVE	
		BURLINGTON MUNICIPAL AIRPORT	
		BURLINGTON, N. C. 27215	
		FAA REPAIR STATION PS4R451M	
		1-800-334-6437	

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
31 July 08		Overhauled propeller m/w HC-F2YL-2	
		S/N FE77 C/W SB 226 RI, 136 I, 118 F, 8 L	
		61-61YR, 154, 177, 223, 228, 217, 229, 282	

SERVICEABLE PART

MANUFACTURER Hartzell
 PART NAME Propeller
 MODEL HC-F2YL-2
 PART NO. FE77
 SERIAL NO. FE77
 REMARKS: Overhauled, C/W SB 226 RI
136 I, 118 F, 8 L 61-61YR, 154, 177,
223, 228, 217, 229, 282, 51, 150 A
AD(07-13-28) greased, printed
and balanced

ACCOMPLISHED BY Joe Crisp

THE AIRCRAFT PROPELLER OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER:

Order No. 716485 Date 31 July 08

Signed Joe Crisp
 Signature of Authorized Representative

FOR: **H & H PROPELLER SERVICE**
 Burlington Municipal Airport
 Burlington, NC 27215

F.A.A. REPAIR STATION NO. PS4R451M;

Painted
Clear
Joe Crisp

RT

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
01-18-11	Hobbs 495.9	TSPOH 0 LH <i>1197.6</i> <i>1197.6 - Correct Hobbs Time after</i> <i>Test Flt. 2/3/11</i>	
Service propellers with Aeroshell#6, Inspect fwd and aft spinner bulkhead and inspect spinner ok.			
I Certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.			
James M. Chrestensen III AP 3507385 IA			<i>James M. Chrestensen III</i>

Q AERO JACKSON Q
JACKSON, MISSISSIPPI

776GA Rt Prop. Date 12-17-2012 Hobbs 540.2 TSO 44.3

/W Annual inspection on prop. Dressed and painted prop.
heldon A Burgess A&P 2159379 IA

heldon A Burgess