


HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-E4N-3Q


PROPELLER S/N HH2445

LOGBOOK # 1

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	SUN AVIATION, INC., Vero Beach, FL (VRB)		
	Date: 3/23/07	Engine Log	N2QE
	Hobbs: 284.4	Eng. Mod: PT6A-42A	SN: 4697247
	Eng. TT: 284.4	Eng. SN PCE-RMO247	In Service 4/5/2006
	ACTT: 284.4		
	Accomplished an Event I and II ANNUAL Inspection IAW FAR 43, appendix "D", using the Piper PA46-500TP inspection checklist, as a guide.		
	C/W 300 Hour Starter Generator Gear Brush Inspection, installed 4 new Brushes PN 200SGL1009.		
	Installed 1 ea new Beta Block PN CA3026. C/W 200 Hour Fuel Nozzle Flow Check & cleaning.		
	Removed Fuel Nozzles, shipped to P&W, Orlando, FL, for inspection, Cleaning and repairs and reinstalled.		
	Re-tensioned A/C Compressor and Alternator Belts. Installed Repaired Fuel Control Assy PN 4138014-1/SN C82058. Rigged and adjusted Engine Controls.		
	MAINTENANCE RELEASE: This aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. All work was performed in accordance with applicable aircraft, engine and or appliance maintenance manuals and instructions. Pertinent details are on file at the repair station office, WO # 22797.		
	AD's Researched THRU Rev. 2007.5		
	Signature 	CRS # ECWR470D	
	Sun Aviation, Inc, Municipal Airport, Vero Beach, FL 32961 (772) 562-9257		

**Naples Air Center, INC.
CRS XO4R655M
230 Aviation Drive North
Naples, Florida 34104
ENGINE LOG**

ACFT: N2QE WO: 10679 DATE: 9-13-07 HOBBS: 196.7
REMOVED PROP HEAT TIMER P/N 691-234 AND REPLACED PROP
HEAT TIMER P/N 691-234. OPERATION CHECK GOOD ON GROUND.
SEE WO# 10679 FOR PERTINENT DETAILS.



RUSS WITT

CRS # X04R655M Naples Air Center, Inc.

SUN AVIATION, INC., Vero Beach, FL (VRB)

Date: 05/27/08 Propeller LOG

Hobbs: 566.6 Model: HC-E4N-3Q

Prop. TT: 566.6 Hub SN: HH2445

ACTT: 566.6

C/W an ANNUAL INSPECTION IAW FAR 43, APPENDIX "D" USING THE Piper PA46-500TP 100 HR Inspection Report as a guide. Dressed Propeller. Bonded prop de-ice boot wires to blades

MAINTENANCE RELEASE: This aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. All work was performed in accordance with applicable aircraft, engine and or appliance maintenance manuals and instructions. Pertinent details are on file at the repair station office, WO # 24224. AD's Researched THRU Rev. 2008.09

Signature 

CRS # ECWR470D

SUN AVIATION, INC., Vero Beach, FL (VRB)

Date: 09/16/08 Propeller LOG N2QE

Hobbs: 665.1 Model: HC-E4N-3Q Aircraft SN: 4697247

Prop. TT: 665.1 Hub SN: HH2445

ACTT: 665.1

C/W with Hartzell Service Letter HC-SL-30-283 by bonding deice boot harness to the blades per accomplishment step 20 (a)-(d) of SL.

MAINTENANCE RELEASE: This aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. All work was performed in accordance with applicable aircraft, engine and or appliance maintenance manuals and instructions. Pertinent details are on file at the repair station office,
WO # 25034

Signature

Sun Aviation, Inc, Municipal Airport, Vero Beach, FL 32961 (772) 562-9257

CRS # ECWR470D

NAPLES AIR CENTER, INC.

CRS X04R655M

230 AVIATION DRIVE SOUTH

NAPLES, FLORIDA 34104

AIRCRAFT: N2QE DATE: 04/15/09 WO: 11285 HOBBS: 853.4 TTSN: 853.4

PROPELLER LOG

THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION PER FAR 43 APPENDIX D, AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. AD'S WERE CHECKED FOR COMPLIANCE THROUGH ISSUE 2009-07. PERTINENT DETAILS OF THIS REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER WORK ORDER 11285.

FOR NAPLES AIR CENTER CRS X04R655M.

ROBERT L. HOUSE